



East Grimstead Chapel Repaired 1838

The interior of the Chapel at East Grimstead which had become much decayed, and was in a very uncomfortable and unwholesome state from damp, was during the autumn of this year thoroughly repaired.

The expense was defrayed by Subscription as stated below.

Although the charge for the repair of the Chancel is not made separately from that of the body of the chapel, it is to be distinctly understood that no portion of the former charge is paid by Parochial Rate, and that all right to the sittings in the Chancel is, as much as ever, reserved to the Rector of the Parish

Individuals Employed			Other Works Carried Out	Cost of Work		
Surname	Given Name	Occupation		£	s.	d.
Beauchamp	James	Carpenter		43	11	1
Crook	John	Mason		12	15	0
			Smith's Work		6	9
			Digging Drain round the Chapel	1	10	0
Total Expense				58	2	10

Source: West Dean St, Andrew Parish Register 1679-1793